



ਦਫਤਰ : ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ, ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ ਭਵਨ ਤੇ ਮਾਰਗ
ਸ਼ਾਖਾ, ਬਰਨਾਲਾ।



ਈਮੇਲ : xenpwdbarnala@yahoo.com

ਵੱਲ,

ਪ੍ਰਿੰਸੀਪਲ,

ਗੁਰਪ੍ਰੀਤ ਹੌਲੀ ਹਾਰਟ ਪਬਲਿਕ ਸਕੂਲ,

ਮਹਿਲ ਕਲਾਂ, ਜਿਲਾ ਬਰਨਾਲਾ।

ਨੰਬਰ 01

ਮਿਤੀ 06-04-2026

ਵਿਸ਼ਾ:-


ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕਰਨ ਸਬੰਧੀ।

ਹਵਾਲਾ:-

ਆਪ ਦੇ ਸਕੂਲ ਦਾ ਪੱਤਰ ਮਿਤੀ 14-03-2026 ਦੇ ਸਬੰਧ ਵਿੱਚ।

ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਅਤੇ ਹਵਾਲੇ ਅਧੀਨ ਪੱਤਰ ਦੇ ਸਬੰਧ ਵਿੱਚ ਆਪ ਨੂੰ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਹਵਾਲੇ ਅਧੀਨ ਨੱਥੀ ਬਿਲਡਿੰਗ ਦੇ ਨਕਸ਼ੇ ਮੁਤਾਬਿਕ ਸਬੰਧਤ ਜੂਨੀਅਰ ਇੰਜੀਨੀਅਰ ਵੱਲੋਂ ਵਿਸ਼ਾ ਅੰਕਿਤ ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਦੀ ਸਾਈਟ ਇੰਨਪੈਕਸ਼ਨ ਕਰਨ ਉਪਰੰਤ ਕੀਤੀ ਗਈ ਸਿਫਾਰਸ ਅਤੇ ਮੰਡਲ ਦਫਤਰ ਵੱਲੋਂ ਜੀ.ਆਰ.ਨੰਬਰ. 971569 ਮਿਤੀ 06-04-2026 ਰਾਹੀਂ 15000/- ਰੁਪਏ ਦੀ ਜਮ੍ਹਾਂ ਕਰਵਾਈ ਗਈ ਫੀਸ ਅਨੁਸਾਰ ਆਪ ਨੂੰ ਸਾਲ 2026-27 (ਮਿਤੀ:31/03/2027 ਤੱਕ) ਦੇ ਸਮੇਂ ਦੀ ਮਿਆਦ ਲਈ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਹੇਠ ਲਿਖੀਆਂ ਸ਼ਰਤਾਂ ਅਨੁਸਾਰ ਜਾਰੀ ਕੀਤਾ ਜਾਂਦਾ ਹੈ:-

- This building safety certificate is issued as per visual inspection and seems safe to occupy for the normal use up to **31-03-2027**.
But parameters to check the actual stability and safety of building such as Architectural Drawings, Bearing capacity, Foundation detail, Structural Drawings, Technical Specifications, Test Reports of Material used, Quality Control reports, certificate from Engineer in Charge for construction etc. are not available.
- In case of any addition, alteration or expansions and modification to this building are done; certificate may be re-obtained after completion from undersigned.
- In case the building is affected by flood or if there is settlement of walls/ foundation or sagging of roofs etc., immediate inspection of the undersigned be arranged to check the stability and safety of the building. It is assured that no stagnant water is on roof of building.
- A separate certificate regarding Fire Fighting should be obtained from the competent authority.
- A separate certificate regard Electrical Works should be obtained from the competent authority.
- The owner of the building/ Management is fully responsible regarding safety of building from all angles in spite of this report.
- The covered area of the building is **57716 Sq.ft.**
- This Report is not valid for legal purpose.
- The Building Certificate should not be considered as NOC for Road Access which will be taken separately by School as per Government policy No. PWDCEH-11012/56/2022-6BR3/2977 Dated, Chandigarh 03.08.2023.
- Any other guidelines as required or amended by the Govt. should be fulfilled & followed from time to time.


ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ, ਲੋ.ਨਿ.ਵਿ.,
ਭ ਤੇ ਮ ਸ਼ਾਖਾ, ਬਰਨਾਲਾ।

ਪਿੱਠ ਅੰਕਣ ਨੰ:

ਮਿਤੀ:

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਮੰਡਲ, ਲੋ.ਨਿ.ਵਿ.(ਭ ਤੇ ਮ) ਸ਼ਾਖਾ ਬਰਨਾਲਾ ਜੀ ਨੂੰ ਉਹਨਾਂ ਦੇ ਦਫਤਰ ਦੇ ਪਿੱਠ ਅੰਕਣ ਨੰਬਰ 06 ਮਿਤੀ 01-04-2026 ਦੇ ਸਬੰਧ ਵਿਚ ਸੂਚਨਾ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ ਜੀ।

-ਸਹੀ-

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ, ਲੋ.ਨਿ.ਵਿ.,
ਭ ਤੇ ਮ ਸ਼ਾਖਾ, ਬਰਨਾਲਾ।

Office: Sub-Divisional Engineer, Provincial Sub-Division, Public Works
Department Building and Roads Branch, Barnala.



Email: xenpwndbarnala@yahoo.com

To

Principal,
Gurpreet Holy Heart Public School,
Mehal Kalan, District Barnala.
Number 01


Date: - 06-04-2026

Subjects: - Regarding issuance of building safety certificate.

Reference: - Regarding your school's letter dated 14-03-2026.

In connection with the above subject and the letter under reference, it is written to you that as per the recommendation made by the concerned Junior Engineer after site inspection of the building of the subject school building as per the building plan attached under reference and as per the fee deposited by the Divisional Office vide G.R. No. 971569 dated 06-04-2026, a Building Safety Certificate is issued to you for the period of the year 2026-27 (up to date: 31/03/2027) as per the following conditions:-

- a) This building safety certificate is issued as per visual inspection and seems safe to occupy for the normal use up to 31-03-2027.
But parameters to check the actual stability and safety of building such as Architectural Drawings, Bearing capacity, Foundation detail, Structural Drawings, Technical Specifications. Test Reports of Material used, Quality Control reports, certificate from Engineer in Charge for construction etc. are not available.
- b) In case of any addition, alteration or expansions and modification to this building are done; certificate may be re-obtained after completion from undersigned.
- c) In case the building is affected by flood or if there is settlement of walls/ foundation or sagging of roofs etc., immediate inspection of the undersigned be arranged to check the stability and safety of the building. It is assured that no stagnant water is on roof of building.
- d) A separate certificate regarding Fire Fighting should be obtained from the competent authority.
- e) A separate certificate regard Electrical Works should be obtained from the competent authority.
- f) The owner of the building/ Management is fully responsible regarding safety of building from all angels in spite of this report.
- g) The covered area of the building is 57716 Sq.ft.
- h) This Report is not valid for legal purpose.
- i) The Building Certificate should not be considered as NOC for Road Access which will be taken separately by School as per Government policy No. PWDCEH-11012/56/2022-6BR3/2977 Dated, Chandigarh 03.08.2023.
- j) Any other guidelines as required or amended by the Govt. should be fulfilled & followed from time to time.


Sub-Divisional Engineer, Provincial Sub-
Division, L.N.V., B.T.M. Branch, Barnala.

Back Number:

Date:-

A copy of the above is sent to the Executive Engineer, Construction Division, L.N.V. (B&M) Branch Barnala for information regarding his office reference number 06 dated 01-04-2026.

Sub-Divisional Engineer, Provincial Sub-
Division, L.N.V., B.T.M. Branch, Barnala